

'63/'64 Studebaker Avanti Filter Exchange Recommendations ⁱ

	<i>Stock</i>	<i>Wix</i>	<i>NAPA</i>	<i>K&Nⁱⁱ</i>	<i>Baldwin</i>	<i>Mobil1</i>	<i>Hastings</i>	<i>Fram</i>	<i>Purolator</i>	<i>AC</i>	<i>Big A</i>	<i>Motor Craft</i>	<i>Mopar</i>	<i>Checker</i>
Oil	AC 3311	51049	1049 ⁱⁱⁱ		B9 or B39	M1-203	212	PH11, (PH 25 R2?)	PER5	3311(OEM) or PF-31	661	FL-2	L-1	C11
Fuel	1558669		3032					G-12 or G-2	GF11	Body GF97 element GF149 ; combined GF6l	159 or 1666			
Air (R1)	1555862		2058 or 2079	E-1560	PA1828		AF127	CA114		AC335C	206	FA41		
Air (R2 uses 2 filters)	1555053	42112	2112	E4600 ^{iv}				CA102 or CA 102PL	AFP58	A176C	1140	9601A		

Notes:

ⁱ Other cross references, both excellent:

<http://www.avantisource.com/interchange.html>

<http://home.comcast.net/~njnagel/files/interchange.pdf>

ⁱⁱWarning, K&N officially states that there are no K&N filters for these vehicles

ⁱⁱⁱ NAPA 1055 is not a legitimate NAPA number

^{iv} Replaces two filters BUT will have to remove canister from engine bay each time you clean and re-oil (every 5 thousand miles)